

***National Spent Nuclear Fuel Program
Meeting Agenda
August 8-9, 2007
Marriott Courtyard
Richland, WA***

Wednesday, August 8

- 8:30 [Introductions](#) Mark Arenaz (NSNFP)
- 8:40 Welcome and Key Initiatives EM (Gary Deleon/Ron Ramsey)
- 9:10 [Actions from January 2007 Meeting](#) NSNFP (Phil Wheatley)
- 9:20 [Repository Program Update](#) RW (Guy Martin)
- Status of Facility Design
 - Status of License Application
- 10:00 Break**
- 10:15 [ID-SR SNF Swap Update](#) EM (Scott DeClue)
- 10:45 [National Spent Nuclear Fuel Program Direction](#) NSNFP (Phil Wheatley)
- FY 2008 Work Planning
- 11:00 [DOE EM License Support and Schedule](#) NSNFP (Linhart/Loo)
- LA Process and NSNFP Coordination
- 11:30 [Technology Development \(EM Style\)](#) DOE-EM (Steve Schneider/Terry Walton)
- Technology Roadmap
- 12:30 Lunch**
- 1:30 Site HLW Progress/Activities
- Focus discussion on HLW issues, qualification of new waste forms
- 1:30 [Hanford](#) DOE-ORP (Albert Kruger)
- 2:00 [SRS](#) [DOE-SR \(John Owens\)](#)
- 2:30 [INL](#) DOE-Idaho (Jan Hagers)
- [HIP Calcine](#)
- 3:15 Break**
- 3:30 Site SNF Progress/Activities
- Focus discussion on interim SNF management plans/issues, and plans for packaging EM SNF in standard canisters, QA programs, etc.
- 3:30 [Hanford](#) DOE-RL (Sen Moy)
- 4:00 SRS DOE-SR (Scott DeClue)
- 4:30 [INL](#) DOE-Idaho (Barb Beller)
- de minimus standards for epoxy fuels at INTEC

5:00 Adjourn

*National Spent Nuclear Fuel Program
Meeting Agenda
August 8-9, 2007
Marriott Courtyard
Richland, WA*

Thursday, August 9

- | | | |
|--------------|---|-------------------|
| 8:15 | Opening Remarks | Mark Arenaz |
| 8:30 | Update on DOE SNF Transportation Topical Report | NSNFP (Tom Hill) |
| 9:00 | Quality Assurance, EM Perspective | EM (Don Armour) |
| 9:30 | Misc SNF Issues | |
| | - Na-Bonded | NSNFP (Henry Loo) |
| | - ANA Development Update | NSNFP (Bill Hurt) |
| | - Al Direct Disposal | (TBD) |
| | - Other issues | |
| 10:15 | Integrated Acceptance Schedule | NSNFP (Bill Hurt) |
| | - Status | |
| 10:30 | Meeting Summary/Actions | Mark Arenaz |
| 11:00 | Adjourn | |
| 12:30 | Tour Hanford Facilities | WTP: Kruger |

FOR THE WTP TOUR, LEATHER BOOTS ARE REQUIRED. THE BOOTS MUST BE AT LEAST ANKLE-HIGH WITH A SUBSTANTIAL SOLE AND FLAT HEEL. NO DRESS BOOTS ARE ALLOWED. YOU MUST ALSO HAVE AT LEAST 4" SLEEVES ON YOUR SHIRTS, AND LONG PANTS.

4:30 Return to Hotel